

ZT Automations, LLC

3) Upper Triangle

Mechanical Assembly of the Upper Triangle Subassembly

Written By: Terence Tam



INTRODUCTION

The Upper Triangle mounts the pulley idler blocks, allowing you to adjust the tension of the drive belts for each arm of the printer.


Along with the Lower Triangle and Drive Towers, the Upper Triangle forms the frame of the printer.



PARTS:

- [Upper Vertexes](#) (3)
- [Nut Spacers](#) (3)
- [360mm OpenBeam](#) (3)
- [Tension Pulley](#) (3)
- [MF83 Ball Bearing](#) (6)
- [Idler Sub Assembly Top/Bottom](#) (6)
- [Idler Sub Assembly Front/Back](#) (6)
- [Vertex End Caps](#) (3)
- [M3 30mm SHC Screws](#) (3)
- [M3 18mm SHC Screws](#) (3)
- [M3 Locknuts](#) (6)
- [M3 8mm SHC Screws](#) (3)
- [M3 Nut](#) (39)
- [M3 Set Screw](#) (12)

Step 1 — Preparing For Assembly




- The components referenced in this document comes from the following kits:
- ZT-KIT-00116 - Chassis Upgrade Kit - Vertexes And Pulley Blocks
- ZT-KIT-00153 - Kossel Sundries - Nut Spacers
- ZT-KIT-00132 - Pulleys
- ZT-KIT-00239 - Kossel Extrusions, Black
- ZT-KIT-00187 / ZT-KIT-00188 - Mini Kossel Extrusions, Clear / Black

Step 2 — Planning For Future Expansion



- Like every T-Slot construction system, it is necessary to pre-plan the insertion of extra nuts for future expansion.
- We suggest inserting a minimum of 6 M3 nuts, to allow for the addition of 2 OpenBeam brackets. You have been supplied with a copious amount of M3 nuts and you may insert more.
- Using the provided set screws, secure the stack of nuts in the center of each extrusion face as shown on the right to prevent rattling and the nuts falling out while maneuvering the extrusion during the build process.

Step 3 — Part Identification: Laser Cut Nut Spacers



- A set of laser cut nut spacers are included in your kit. These spacers positions the nuts at the correct spacing on the extrusion to allow for ease of assembly.
- Kossel Pro Upper Vertex.
- Kossel Pro Lower Vertex / Kossel Reprap Vertexes
- Vertical Drive Tower

Step 4 — Slide Nuts And Spacers Onto Extrusion





- ★ Remember to preload the nuts to the center of the extrusion, as almost all the channels are capped off after installation!
- Install the spacer and nut stack as shown to the right, using the spacers meant for the Kossel Pro Lower Vertex, on both ends of each of the extrusions.

Step 5 — Install Extrusion End Cap



- These Extrusion End Caps make it easier to load nuts into the channels.
- Insert the pin on the extrusion end cap into the hole on the OpenBeam Extrusion as shown to the right.

Step 6 — Slide On Vertex



- Carefully slide into Vertex.
- Secure with 2x M3 x 8mm SHCS on each OpenBeam extrusion, 6 sides total, using the included ball-head 2.5mm hex driver.
- Repeat for all 3 pieces of OpenBeam extrusion and all 3 vertexes.

Step 7 — Install Vertex Cap Plate




- Using M3 x 6mm Button Head Cap Screws (BHCS), install vertex cap plates over the end of each vertex.

Step 8 — Insert Pulley Bearings



- Insert 2x MF83 Bearing into both sides of the GT2 pulleys.

Step 9 — Idler Blocks - Part 1



- Insert an Idler Subassembly front/back into an Idler Subassembly top/bottom, with the nut cutout facing out and closer to the bottom.
- Repeat to create a total of 3 subassemblies.

Step 10 — Idler Blocks - Part 2



- Insert an M3 30mm SHC Screw into the Idler Subassembly Front/Back, then slide a pulley onto it with the thick end facing the narrow side of the Idler Subassembly Top/Bottom.

Step 11 — Idler Blocks - Part 3



- Slide another Idler Subassembly Front/Back onto the screw. Follow that with an M3 Locknut.


Step 12 — Idler Blocks - Part 4



- Using one of the Idler Subassembly Top/Bottom that has had an M3 Locknut glued in place, add it to the top of the assembly and tighten the 30mm screw. Ensure that the pulley still spins freely.

⚠ Do Not Over Tighten The 30mm Screw!

Step 13 — Install Idler Blocks



- Slide an idler block into the vertex. There is only one way the assembly will fit. Make sure that the side with the Locknut is facing inward toward the vertex cap.
- Using an M3 18mm SHC screw, loosely screw each of the idler blocks into the vertex caps.

Step 14 — Assembly Preparation



- Insert an M3 8mm SHC screw into each of the corner vertexes, while loosely tightening an M3 Nut on the inside.
- Set the Upper Triangle aside, we'll use it during the final assembly.

